

1.) CONVEYOR MOTION CONTROLLED BY COMPUTER

- Encoder
- Variable Speed
- Stop / Start
- 2.) OPERATOR PLACES PRODUCT ON INFEEED


 - Flat
 - Thickest Point Near Centerline
 - Product Spaced Apart So That Load Cell Sees Only One At The Time
 - Product Recognized
 - Dimensional Measurements
 - Thickest Point
 - Length & Width
 - Template, etc...

- 4.) LOAD CELL

 - Belt Is Unsupported

- 5.) TEMPERATURE PROBE:

 - Vertical Motion Axis
 - Computer Engages Probe When Product's Thickest Point Is Under (5a)
 - Probe Dwell Is Long Enough For Good Temperature Measurement (5b)



PROCESSING EQUIPMENT SOLUTIONS, INC.			
REVISION	REV 1	Item #	Zone - Auto -
1	1 of 1	NSA	
Revised	Approved	Get SP	
	Design	Print	
	Checklist	Checklist	
	Comments	Comments	
	Customer	Customer	
	Phone (770) 500-8737	Phone (770) 500-8737	
	Fax (770) 500-8737	Fax (770) 500-8737	
			N/A

NOTES:

Quality Control
Conveyor